

Address  
Donaldson Europe BV  
Research Park Building No. 1303  
Interleuvenlaan 1  
B-3001 Leuven (Heverlee)  
Belgium

Date  
20 June 2025

### **CLP Regulation (2008)**

To Whom It May Concern,

Following the introduction of the CLP Regulation in the European Union which is defined as follow:

The CLP Regulation (2008) is an EU law that ensures hazardous chemicals are properly classified, labelled, and packaged to protect human health and the environment in line with the UN's Globally Harmonised System (GHS).

Donaldson Filtration must comply, affecting coolant filters with additives, which require new labels and part numbers. As a result, low-volume and dated coolant additive filters for older applications will be discontinued. The changes ensure regulatory compliance but necessitate the cancelation of older filter models in Europe Distribution Centre.

*Note: All cancelled parts without an alternative can be replaced with the non-additive (blank) parts active in the region.*

### Cancelled with a Replacement

| Superseded Part Number | New Part Number         |
|------------------------|-------------------------|
| Base item              | Base item CLP compliant |
| P550866                | P550867                 |
| P552070                | P768192                 |
| P552071                | P768192                 |
| P552073                | P768193                 |
| P552074                | P768194                 |
| P552075                | P768195                 |
| P552076                | P768196                 |
| P552096                | P768186                 |
| P554071                | P768187                 |
| P554072                | P768188                 |
| P554073                | P768189                 |
| P554074                | P768190                 |
| P554075                | P768191                 |
| DBC4088                | P768187                 |
| P552055                | P960120                 |

### Canceled with no replacement

| Canceled Part Number | New Part Number    |
|----------------------|--------------------|
| Base item            | No CLP Replacement |
| P552106              | No Replacement     |
| P554019              | No Replacement     |
| P554422              | No Replacement     |
| P554860              | No Replacement     |

Thuto Sekgetho  
 Product Manager Mobile Solutions Aftermarket – Engine Liquid  
 Donaldson EUROPE b.v.  
 Research Park Zone 1303  
 Interleuvenlaan 1  
 B-3001 Leuven, Belgium

**Regional Headquarters – Europe, Middle East and Africa:** Leuven, Belgium

**Manufacturing Facilities:** France - Germany - Italy - United Kingdom - Czech Republic – South Africa - Poland

**Distribution Centres:** Belgium – South Africa

**Sales Offices:** Austria - Belgium - Czech Republic - Denmark - France - Germany - Hungary - Italy - Poland - Slovakia - Spain - Sweden - Switzerland - The Netherlands - Turkey - United Arab Emirates - United Kingdom – South Africa